

Service & Repair History

<u>Check Records</u>



**Odometer Records Check** 

<u>Check Records</u>




# **VIN:** 1GBLP37J9W3311057

## Year: 1998 Make: Chevrolet Model: P30

Details info. on VIN: 1GBLP37J9W3311057 Engine\_description: 7.4L V8 OHV 16V Year: 1998 Make: Chevrolet Engine\_capacity: 7.4 L Body\_type: MOTORHOME Fuel\_type: Gasoline Model: P30 Manufacturer: General Motors Company Drive\_type: RWD Country: United States Vin: 1GBLP37J9W3311057 Doors: 2 Engine\_size: 7.4 Engine\_number\_of\_cylinders: 8 Displacement\_(cc): 7440 Displacement\_(ci): 454 Engine\_model: V8 Region: North America Note: Manufacturer Builds More Than 500 Vehicles Per Year Source: USDecode

Accident & Title History

<u>Check Records</u>



Market Value Fair Price

<u>Check Records</u>

Selling your Vehicle?

The sticker on the window is a rich source of essential information about your automobile. The window sticker lets

your buyer know exactly what's included particularly in your car.

#### View our Sample Window Sticker Get your Windows Sticker



## SERVICE MAINTENANCE RECORDS

For your Vehicle 1998 CHEVROLET P30

At the Mileage of 55000 mi

Against the VIN 1GBLP37J9W3311057

#### A QUICK SUMMARY OF YOUR VEHICLE

If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.

## SAFETY RECALLS 2 items

Your vehicle has 2 Safety Recalls. These are announcements made by your vehicle's manufacturer that there is a safety-related problem that needs immediate repair and should be repaired free of charge by your vehicle's dealership.

### → <u>View your recall notices here.</u>

#### WARRANTY STATUS

Below is your default warranty information. This excludes any additional warranty coverage you may have purchased.

Basic new car warranty 3 years

Powertrain warranty 3 years

× Federal emissions warranty 8 years

If the vehicle is covered.

If the vehicle is not completely covered.

If the vehicle is not covered.

By analyzing other vehicles of the same year make model our results show you may need the following repairs in the next 12

months. It is recommended that you have these parts inspected by a trusted technician, and replace as needed.

36%	27%
Likelihood of	Likelihood of
Replace Mass Air Flow (MAF) Sensor	Replace Oxygen Sensor(s) (O2S)
\$443	\$223
Cost of repair	Cost of repair
\$341 in parts	\$121 in parts



This information can help you make strategic decisions about bidding and budgeting by showing you where you're succeeding and where you may be missing opportunities for improved performance.

Jpgrade your Report

This Vehicle History Report Report is based only on information acquirable by Vehicle History Report as at the time of generating this report. Note that other information about this vehicle, including problems and services, may not have been reported to Vehicle History Report. You are strongly advised to use this report only as an additional but important tool, along with the vehicle inspection and test drive, to make an informed decision about the purchase of this vehicle. © 2022 Vehicle History Report. All Rights Reserved.